

~~SECRET~~

25X1

25X1

This document contains

3 pages.

EVALUATION SUMMARY

Mission BX-6847

0-18-200511- 08

Copy 8 of 9 copies

13 February 1968

1. Processing and Titling - Good (Field)
2. Physical Condition - Fair to good
3. Hypo Retention Rewashing required (Patch 3-4)
4. Exposure(based on density) - Medium
5. General Comments:
 - A. Five parts required dual printing.
 - B. Small amounts of pinholes, kinks and embedded dirt are noted throughout the mission.
 - C. Parts 5-9 were 100% clouds/water.
 - D. Base plus fog average .34.
 - E. Part 16 was received with several kinks, scratches, etc.
 - F. Most parts contain fine intermittent emulsion scratches from head to tail.

~~SECRET~~

25X1

MISSION NO. BX-6847 EVALUATION REPORTEvaluated By Q.C. TechniciansCamera Fwd/AftEvaluation Date 31 January 1968Emulsion 3404

Film Metering	Normal
Film Tracking	Normal
Clock Exposure	Light to medium
Counter Operation	Good
Data Chamber (image quality)	Good
Apparent Resolution	Normal
Apparent Granularity	Normal
Density	Low to medium
Contrast	Medium to high

Discrepancies:

<u>Part</u>	<u>Frames</u>	<u>Comments</u>
1	2,23,75 76	Handling marks HT2 test spot
2	77-151 123,151, 137,144	Minus density streak on all Fwd frames Creases
3	203-206	Splice
4	246	Handling marks
5	325-328	Splice
6	387	Emulsion dig
7	485	Minus density spots
8	608 607	Crease Severe abrasion
9	609-610	HT2 test spot
10	616,662,683	Emulsion dig
11	762 824 761-835	Emulsion pickoff Emulsion dig Minus density streak (Fwd frames only)

~~SECRET~~


25X1



Discrepancies (Cont'd) Camera

<u>Part</u>	<u>Frames</u>	<u>Comments</u>
12	876 898	Emulsion dig Abrasions
13	987	Handling marks
14	1005-1010 1014	Edge static
15	1066 1140	Handling marks Emulsion rub
16	1154,1215 1158 1155-1158	Crease Abrasions Splice
17	1227-1244 1240 1259-1262	Chemical stain Ultrasonic splice Splice

~~SECRET~~



25X1